



PERFORMANCE ADVANTAGE COMPANY

www.pactoolmounts.com



5-2015

INS-LE-1005

RIFLE VERTICAL MTG. KIT**P/N LE-1005****INSTALLATION INSTRUCTIONS**

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com

CAUTION

To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.

- * The bracket must be securely mounted to a stable surface and material.
- * When mounting bracket to PAC TRAC aluminum products **P/N 7000**, **P/N 7020**, **P/N 7040**, **P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- * PAC recommends regular and frequent inspections to be certain of proper operation and installation.

**VERTICAL MOUNTING KIT**

MTG. HARDWARE PAC Fasteners – PAC TRAC Mounting			QTY
	P/N 2049	#10-24 x 3/4 S.S. Pan Head Screw (P/N SC-1900)	2
	P/N 7016	Trac Lok Insert	4
	P/N 2046	#10-24 x 1 S.S. Pan Head Screw (P/N 1005-B)	2





FIGURE 2
(PAC TRAC Mounting)



PERFORMANCE ADVANTAGE COMPANY

www.pactoolmounts.com



5-2015

INS-LE-1005

RIFLE VERTICAL MTG. KIT**P/N LE-1005****INSTALLATION INSTRUCTIONS**

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com

CAUTION

To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.

- * The bracket must be securely mounted to a stable surface and material.
- * When mounting bracket to PAC TRAC aluminum products **P/N 7000**, **P/N 7020**, **P/N 7040**, **P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- * PAC recommends regular and frequent inspections to be certain of proper operation and installation.



MTG. HARDWARE			QTY
PAC Fasteners – Through Mounting			
	P/N 2049	#10-24 x 3/4 S.S. Pan Head Screw (P/N SC-1900)	2
	P/N 2049LN	#10-24 S.S. Locking Hex Nut	4
	P/N 2046	#10-24 x 1 S.S. Pan Head Screw (P/N 1005-B)	2




FIGURE 1
(Thru Mounting Method)