



AMKUS CUTTER KIT

P/N K5022

INSTALLATION INSTRUCTIONS

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com

CAUTION

To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.

- * The bracket must be securely mounted to a stable surface and material.
- * When mounting bracket to PAC TRAC aluminum products **P/N 7000**, **P/N 7020**, **P/N 7040**, **P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- * PAC recommends regular and frequent inspections to be certain of proper operation and installation.

STANDARD MTG. HARDWARE

QTY

 P/N 3017 1/4-20 x 1 S.S.
S.S. Pan Head Screw

2

 P/N 2069LN 1/4-20
Nylon Locking Nut

2

SUPER ADJUST.

STANDARD MTG. HARDWARE

QTY


 P/N 2031 1/4-20 x 1
S.S. Flat Head Screw

3

 P/N 2069LN 1/4-20
Nylon Locking Nut

3

BASE



SUPER ADJUSTAMOUNT ATTACHMENT

(See INS-K5050 for more installation information)





FIGURE 1

(Thru Mounting Method)

**AMKUS CUTTER KIT****P/N K5022****INSTALLATION INSTRUCTIONS**

For additional assistance call 888-514-0083 between 8AM-5PM EST or email: info@pactoolmounts.com

CAUTION

To avoid the risk of personal injury, property damage or product damage, please use the included fasteners for mounting.


- * The bracket must be securely mounted to a stable surface and material.
- * When mounting bracket to PAC TRAC aluminum products **P/N 7000**, **P/N 7020**, **P/N 7040**, **P/N 7050** with the included Trac Lok inserts **P/N 7016**, torque the screws to a maximum 15 in-lbs.
- * PAC recommends regular and frequent inspections to be certain of proper operation and installation.

MTG. HARDWARE for PAC TRAC			QTY
	P/N 2049	#10-24 x 3/4 S.S. S.S. Pan Head Screw	2
	P/N 7016	Trac Lok Insert	2

SUPER ADJUST.

MTG. HARDWARE for PAC TRAC			QTY
	P/N 2044	#10-24 x 1 S.S. Flat Head Screw	3
	P/N 2054	#10 S.S. Washer	3
	P/N 7016	Trac Lok Insert	3

BASE



SUPER ADJUSTMENT ATTACHMENT
(See INS-K5050 for more installation information)





FIGURE 2
(PAC TRAC Mounting)